

Guide to Apparel/Textile Care Label Symbols



Guide to Apparel/Textile Care Label Symbols



US Market: ASTM D5489 FU Market: Managed by Ginetex **** Water Temperatures (maximums) Water Temperatures (maximums) (200F) (160F) (140F) (120F) (105F) (65-85F) added to symbol 95C 70C 60C 50C 40C 30C (200F) (160F) (140F) (120F) (105F) (65-85F) . . . wash press aentle WASH process wash process process wash only oxygen/ **BLEACH** oxygen bleach agent allowed bleach allowed the shade dry in the the shade dry in the tumble norma press dry gentle/ tumble max 60° shade shade delicate dry DRY Low - Max Temp Medium -Max Temp High - MaxTemp no steam Max Temp Max Temp Max Temp Do Not Iron do not iron **IRON** 110C (230F) 150C (300F) 200C (390F) (added to iron) 110C(230F) 150C (300F) 200C (390F) normal process normal process do not dry clean **PROFESSIONAL** any solvent gentle solvent Professional dry cleaning in hydrocarbons Professional dry cleaning in tetrachloroethene **DRYCLEAN** mild cycle petroleum or silicone petroleum or silicone dryclean (distillation temperature between 150C and 210C, flash point between 38C and 70C) and all solvents listed for the symbol F solvent only solvent only mild cycle PROFESSIONAL very mild cycle WETCLEAN normal cycle mild cycle do not wet clean normal process mild process very mild process do not wet clean

Symbols must be sequenced in the following order: Washing, Bleaching, Drying, Ironing, Professional Care. Additional symbols not shown on this document may be required to comply with regulations.

©2015 Eurofins. All rights reserved. We are pleased to provide limited technical and professional information to our valued customers. However, this publication does not represent any applicable legal or regulatory requirements and is intended only for educational purposes. It does not constitute consultative or professional advice.